

Appendix 6:

Annual Rehabilitation Report

Summary Table

Annual Rehabilitation Report Form, Rehabilitation Maps and Rehabilitation Summary

Annual Rehabilitation Report Form – Mines

Year Ending: 2019

Mine: Mt Thorley Warkworth

Company: Yancoal Australia

Plans Attached:

Mt Thorley Warkworth – AER 2019

Approved Mining Operations Plan:

MTW MOP Amendment B (2015 – 2021) – Approval Date 11/06/2019

Total Area Covered by Mining Operations Plan:

MTW MOP – 6,185ha

Total Area Covered by Mining Lease for This Mine: 6,185ha

Table 1: Rehabilitation Progress 2019

Rehabilitation Activity Type	Domain Identifier	Primary Domain	Secondary Domain	Total Area Last Reported (ha)	Total Area to date (ha)
1.1 Active mining and infrastructure area, facilities, including roads and tracks	1A	Final Void	Final Void	312.8	373.0
	2C	Water Management Areas	Rehabilitation Area - Grassland	42.0	42.1
	2E	Water Management Areas	Rehabilitation Area - Woodland EEC	22.8	22.8
	3C	Infrastructure Area	Rehabilitation Area - Grassland	100.7	100.6
	3E	Infrastructure Area	Rehabilitation Area - Woodland EEC	68.6	68.5
	4C	Tailings Storage Facility	Rehabilitation Area - Grassland	75.7	76.4
	4D	Tailings Storage Facility	Rehabilitation Area - Woodland	11.7	11.7
	4E	Tailings Storage Facility	Rehabilitation Area - Woodland EEC	88.3	88.3
	5C	Overburden Emplacement Area	Rehabilitation Area - Grassland	364.4	363.2
	5D	Overburden Emplacement Area	Rehabilitation Area - Woodland	256.1	242.1

Rehabilitation Activity Type	Domain Identifier	Primary Domain	Secondary Domain	Total Area Last Reported (ha)	Total Area to date (ha)
	5E	Overburden Emplacement Area	Rehabilitation Area - Woodland EEC	1248.1	1191.1
	Total Active			2591.2	2579.8
1.2 Decommissioning	Total - Decommissioning			0.0	0.0
1.3 Landform Establishment	4C	Tailings Storage Facility	Rehabilitation Area - Grassland		0.1
	4E	Tailings Storage Facility	Rehabilitation Area - Woodland EEC		0.2
	5C	Overburden Emplacement Area	Rehabilitation Area - Grassland		3.2
	5D	Overburden Emplacement Area	Rehabilitation Area - Woodland		2.7
	5E	Overburden Emplacement Area	Rehabilitation Area - Woodland EEC		18.0
		Total - Landform Establishment			93.1 (included in 1.1)
1.4 Growth Medium Development	2C	Water Management Areas	Rehabilitation Area - Grassland		1.2
	2E	Water Management Areas	Rehabilitation Area - Woodland EEC		2.9
	4E	Tailings Storage Facility	Rehabilitation Area - Woodland EEC		4.0
	5C	Overburden Emplacement Area	Rehabilitation Area - Grassland		18.9
	5D	Overburden Emplacement Area	Rehabilitation Area - Woodland		26.1
	5E	Overburden Emplacement Area	Rehabilitation Area - Woodland EEC		81.8
		Total - Growth Medium Development			4.3 (included in 1.1)
1.5 Ecosystem and Land Use Establishment	1A	Final Void	Final Void		1.5
	2C	Water Management Areas	Rehabilitation Area - Grassland	1.2	1.6
	2E	Water Management Areas	Rehabilitation Area - Woodland EEC	2.9	3.3
	3C	Infrastructure Area	Rehabilitation Area - Grassland		5.4
	3E	Infrastructure Area	Rehabilitation Area - Woodland EEC		0.5
	4C	Tailings Storage Facility	Rehabilitation Area - Grassland		26.4
	4D	Tailings Storage Facility	Rehabilitation Area - Woodland		1.4

Rehabilitation Activity Type	Domain Identifier	Primary Domain	Secondary Domain	Total Area	Total Area	
				Last Reported (ha)	to date (ha)	
	4E	Tailings Storage Facility	Rehabilitation Area - Woodland EEC	4.0	35.2	
	5C	Overburden Emplacement Area	Rehabilitation Area - Grassland	35.9	567.5	
	5D	Overburden Emplacement Area	Rehabilitation Area - Woodland	28.4	52.8	
	5E	Overburden Emplacement Area	Rehabilitation Area - Woodland EEC	95.5	446.7	
	Total - Ecosystem and Land Use Establishment			167.9	1142.3	
1.6 Ecosystem and Land Use Development	1A	Final Void	Final Void	1.8	0.0	
	2C	Water Management Areas	Rehabilitation Area - Grassland	1.8	0.0	
	2E	Water Management Areas	Rehabilitation Area - Woodland EEC	3.3	0.0	
	3C	Infrastructure Area	Rehabilitation Area - Grassland	5.4	0.0	
	3D	Infrastructure Area	Rehabilitation Area - Woodland	1.5	0.0	
	3E	Infrastructure Area	Rehabilitation Area - Woodland EEC	0.5	0.0	
	4C	Tailings Storage Facility	Rehabilitation Area - Grassland	27.3	0.0	
	4D	Tailings Storage Facility	Rehabilitation Area - Woodland	1.4	0.0	
	4E	Tailings Storage Facility	Rehabilitation Area - Woodland EEC	35.5	0.0	
	5C	Overburden Emplacement Area	Rehabilitation Area - Grassland	550.4	0.0	
	5D	Overburden Emplacement Area	Rehabilitation Area - Woodland	43.7	0.0	
	5E	Overburden Emplacement Area	Rehabilitation Area - Woodland EEC	395.3	0.0	
		Total - Ecosystem and Land Use Development			961.1	0.0
	1.7 Rehabilitation Complete	Total - Rehabilitation Complete			0.0	0.0
1.8 Total Area Disturbed (items 1.1 to 1.7)	1A	Final Void	Final Void	314.6	374.5	
	2C	Water Management Areas	Rehabilitation Area - Grassland	45.0	44.9	
	2E	Water Management Areas	Rehabilitation Area - Woodland EEC	29.0	29.0	
	3C	Infrastructure Area	Rehabilitation Area - Grassland	106.1	106.0	
	3D	Infrastructure Area	Rehabilitation Area - Woodland	1.5	0.0	

Rehabilitation Activity Type	Domain Identifier	Primary Domain	Secondary Domain	Total Area Last Reported (ha)	Total Area to date (ha)
	3E	Infrastructure Area	Rehabilitation Area - Woodland EEC	69.1	69.0
	4C	Tailings Storage Facility	Rehabilitation Area - Grassland	103.0	102.9
	4D	Tailings Storage Facility	Rehabilitation Area - Woodland	13.1	13.1
	4E	Tailings Storage Facility	Rehabilitation Area - Woodland EEC	127.8	127.7
	5C	Overburden Emplacement Area	Rehabilitation Area - Grassland	950.7	952.8
	5D	Overburden Emplacement Area	Rehabilitation Area - Woodland	328.2	323.7
	5E	Overburden Emplacement Area	Rehabilitation Area - Woodland EEC	1738.9	1737.6
	Total Footprint			3827.0	3881.2

Table 2: Soil Management and Erosion, 2019

Soil Stockpiling/ Use	Soil Used This Period (m3)	Soil Pre-stripped This Period (m3)	Stockpile Inventory to Date (m3)	Soil Stockpiled Last Report (m3)
	68,500	40,030	660,357	688,826
2.2 Erosion Treatment	Total Area to Date (ha)	Total Area Last Report (ha)	Total Area This Report (ha)	Area Retreated This Period (ha)
Approx. area of sheet or gully erosion requiring reshaping topdressing and/or resowing	Not Available	21.7	6.0	3.5

Table 3: Weed Control

	Area (ha)
3.1 Approx. area adversely affected by weeds as of the date of this report	Not Available
3.2 Area treated for weed control during the period covered by the report	336.0
3.3 Give summary of control strategies used and verification by approval agency(s)	
Species targeted in rehabilitation areas during 2019 included: <i>Galenia pubescens</i> , Rhodes grass, green panic, <i>Acacia saligna</i> , mustard weed (Brassica), farmers friend (<i>Bidens pilosa</i>) and paddys lucerne (<i>Sida rhombifolia</i>). 164.5ha treated for weed control using boom spray or wick wiper treatment; 171.5ha treated for weed control using Quikspray units or backpack sprays.	

Table 4: Management of Rehabilitation Areas

4.1 Area treated with maintenance fertiliser	0ha
4.2 Area treated by rotational grazing, cropping or slashing	90ha
Give Summary	90ha Warkworth rehabilitation area licence agreement in place for grazing.

Table 5 Variations to Rehabilitation Program

Has rehabilitation work proceeded generally in accordance with the conditions of an accepted Mining Operations Plan?	Yes
If not please cite any approval granted for variations, or briefly describe the seasonal conditions or other reasons for any changes and the nature of any changes which have been made.	NA

Table 6: Planned Operations During the Next Report Period

6.1 Area estimated to be disturbed	60ha
6.2 Area estimated to be rehabilitated	64ha

Appendix 7:

Rehabilitation and

Disturbance Summary

NPN RL175 Geofluv

Tailings Dam 2

CD RL180 Geofluv Topsoil A

CD RL160 Stockpile Area

CD RL180 Topsoil A

CD RL190 Topsoil A

CD RL180 Geofluv Topsoil B

CD RL180 Topsoil B

CD RL190 Spoil/Compost

CD RL185

Woodlands RL155

MTO Geofluv RL130 Topsoil A

MTO Geofluv RL130 Topsoil B

MTO RL154 Geofluv Topsoil B

MTO RL154 Geofluv Topsoil C

MTO RL154 Topsoil A

MTO RL154 Geofluv Topsoil A

MTO RL154 Topsoil B

MTO RL154 Topsoil C

MTO RL154 Topsoil D

MTO RL154 Spoil/Compost

MTO RL154 Topsoil E



MTW Rehabilitation Areas 2019

MTW

File:MTW Rehab Areas 2019.wor
MTW Rehab Areas 2019.PDF

Date: 06/03/2020
Produced By: BB
Map Size: A4 Portrait
Coordinate System: MGA94 Zone 56
Revision: 01
Data Source: Various

DISCLAIMER
Yancoal makes every effort to ensure the quality of the information available on this map. Before relying on the information on this plan, users should carefully evaluate its accuracy, currency, completeness and relevance for their purpose and should obtain any appropriate professional advice relevant to their particular circumstances. Yancoal cannot guarantee and assumes no responsibility for the accuracy, currency or completeness of the information and by using this map you accept that Yancoal has no liability for any loss or damage in any form whatsoever caused directly or indirectly from the use of this map. © Yancoal Australia. All boundaries shown should be considered approximate only and subject to survey.

MTW Annual Review Appendix 2 – Rehabilitation Summary

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
CD RL160 Stockpile Area	Woodland	318,885.56 E 6,390,194.33 N	0.7	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform is flat in this area, no aspect. ▪ Area is flat and hence not requiring drainage controls. ▪ Landform surface preparation comprised minor shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Area was an old topsoil stockpile so there was remaining Clay loam/sandy clay loam topsoil from the floor of the stockpile at a nominal thickness of 100mm. ▪ Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. ▪ Growth medium preparation included ameliorant incorporation and aerating as required ▪ The area was sown in December with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
CD RL180 Geoflur Topsoil A	Woodland	318,926.55 E 6,389,856.67 N	8.0	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform has been designed using a geomorphological landform approach based on alluvial analogues. Typical slope of the landform is 10 to 14 degrees with limited areas at 16 to 18 degrees. The slope has a primarily easterly aspect. ▪ Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the east. ▪ Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. ▪ Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. ▪ Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> The area was sown in September with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement. Selective weed control of mainly <i>Galenia pubescens</i> was undertaken after desirable native species and weed species had started to germinate.
CD RL180 Geofluv Topsoil B	Woodland	319,068.55 E 6,389,506.31 N	0.7	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform has been designed using a geomorphological landform approach based on alluvial analogues. Typical slope of the landform is 10 to 14 degrees with limited areas at 16 to 18 degrees. The slope has a primarily easterly aspect. Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the east. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in September with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement. Selective weed control of mainly <i>Galenia pubescens</i> was undertaken after desirable native species and weed species had started to germinate.
CD RL180 Topsoil A	Woodland	319,280.83 E 6,389,697.26	4.1	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. Typical slope of the landform is 10 degrees with a primarily northerly aspect. Drainage is via westerly draining contours reporting to an engineered rock-lined chute. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in September with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement. Selective weed control of mainly <i>Galenia pubescens</i> was undertaken after desirable native species and weed species had started to germinate.
CD RL180 Topsoil B	Woodland	319,221.33 E 6,389,562.33 N	1.3	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. Typical slope of the landform is 10 degrees with a primarily northerly aspect. Drainage is via westerly draining contours reporting to an engineered rock-lined chute. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in September with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement. Selective weed control of mainly <i>Galenia pubescens</i> was undertaken after desirable native species and weed species had started to germinate.
CD RL185	Woodland	320,207.39 E 6,389,707.77 N	8.8	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. Typical slope of the landform is 10 degrees with a primarily southerly aspect. Drainage is via easterly draining contours reporting to adjacent existing contour drainage and then to an engineered rock-lined chute.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in December with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
CD RL190 Spoil/Compost	Woodland	319,632.10 E 6,389,688.05 N	5.2	<ul style="list-style-type: none"> The landform is flat in this area, no aspect. Area is flat and hence not requiring drainage controls. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. No topsoil was added, spoil has been used as the growth medium. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in December with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
CD RL190 Topsoil A	Woodland	319,443.37 E 6,389,707.77 N	5.2	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. Typical slope of the landform is 10 degrees with a primarily northerly aspect. Drainage is via easterly draining contours reporting to an engineered rock-lined chute. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in December with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO Geofluv RL130 Topsoil A	Woodland	319,784.64 E 6,387,557.34 N	0.1	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform has been designed using a geomorphological landform approach based on alluvial analogues. This small section of landform has a typical slope of 22 degrees. The slope has a primarily northerly aspect. Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the east. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Sandy topsoil with a high amount of woody mulch was spread directly from stripping areas at a nominal thickness of 100mm. Soil ameliorants were not applied due to the slope being too steep for access by spreaders. The area was sown by hand in December with Diverse Native Woodland at 15.7kg/ha.
MTO Geofluv RL130 Topsoil B	Woodland	319,802.28 E 6,387,509.92 N	4.9	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform has been designed using a geomorphological landform approach based on alluvial analogues. Typical slope of the landform is 10 to 14 degrees. The slope has a primarily north-easterly aspect. Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the north. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> ▪ Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required ▪ The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Geofluc Topsoil A	Woodland	319,845.67 E 6,386,872.08 N	1.6	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform has been designed using a geomorphological landform approach based on alluvial analogues. This section of the landform is flat and therefore without any aspect. ▪ Area is flat and hence not requiring drainage controls. ▪ Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. ▪ Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. ▪ Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required ▪ The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Geofluc Topsoil B	Woodland	320,012.22 E 6,387,049.56 N	12.2	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform has been designed using a geomorphological landform approach based on alluvial analogues. Typical slope of the landform is 10 to 14 degrees. The slope section has a primarily northerly aspect. There is also a flat section of landform above the slope. ▪ Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the north. ▪ Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Geofluv Topsoil C	Woodland	320,093.04 E 6,387,041.13 N	1.9	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform has been designed using a geomorphological landform approach based on alluvial analogues. This section of the landform is flat and therefore without any aspect. Area is flat and hence not requiring drainage controls. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam topsoil from stripping areas in West Pit South was spread directly at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Spoil/Compost	Woodland	320,311.38 E 6,385,990.70 N	5.1	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. Typical slope of the landform is 10 degrees with a primarily southerly aspect. Drainage is via westerly draining contours reporting to an engineered rock-lined chute. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. No topsoil was added, spoil has been used as the growth medium. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> ▪ Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required ▪ The area was sown in November with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Topsoil A	Woodland	319,611.14 E 6,386,649.08 N	2.3	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform is flat in this area, no aspect. ▪ Area is flat and hence not requiring drainage controls. ▪ Landform surface preparation comprised minor shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Clay loam topsoil from stripping areas in West Pit South was spread directly at a nominal thickness of 100mm. ▪ Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. ▪ Growth medium preparation included ameliorant incorporation and aerating as required ▪ The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Topsoil B	Woodland	319,538.68 E 6,386,642.15 N	2.1	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform is flat in this area, no aspect. ▪ Area is flat and hence not requiring drainage controls. ▪ Landform surface preparation comprised minor shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Clay loam/sandy clay loam topsoil from existing topsoil stockpiles (sourced from rehabilitation disturbance) was spread at a nominal thickness of 100mm. ▪ Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. ▪ Growth medium preparation included ameliorant incorporation and aerating as required

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Topsoil C	Woodland	319,613.39 E 6,386,416.30 N	0.8	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform is flat in this area, no aspect. Area is flat and hence not requiring drainage controls. Landform surface preparation comprised minor shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam topsoil from stripping areas in West Pit South was spread directly at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation and aerating as required The area was sown in November with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Topsoil D	Woodland	319,747.84 E 6,386,141.08 N	1.4	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform is flat in this area, no aspect. Area is flat and hence not requiring drainage controls. Landform surface preparation comprised minor shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles (sourced from rehabilitation disturbance) was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation and aerating as required The area was sown in November with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
MTO RL154 Topsoil E	Woodland	319,821.58 E 6,386,085.74 N	6.5	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ Typical slope of the landform is 10 degrees with a primarily southerly aspect. ▪ Drainage is via westerly draining contours reporting to an engineered rock-lined chute. ▪ Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Clay loam topsoil from stripping areas in West Pit South was spread directly at a nominal thickness of 100mm. ▪ Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. ▪ Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required ▪ The area was sown in November with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
NPN RL175 Geofluv	Woodland	317,038.19 E 6,392,473.36 N	3.4	<ul style="list-style-type: none"> ▪ The landform was constructed from a waste emplacement. ▪ The landform has been designed using a geomorphological landform approach based on alluvial analogues. Typical slope of the landform is 10 to 14 degrees with limited areas at 16 to 22 degrees. The slope has a primarily northerly aspect. ▪ Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the north west. ▪ Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. ▪ Sandy topsoil with a high amount of woody mulch was spread directly from stripping areas at a nominal thickness of 100mm. High amount of mulch was used for erosion protection on slopes. ▪ Soil ameliorant comprising recycled gypsum compost was applied at a rate of 5t/ha. No compost was used due to high organic component in topsoil. ▪ Growth medium preparation included ameliorant incorporation, and aerating as required

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	Rehabilitation Summary
				<ul style="list-style-type: none"> The area was sown in September with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement. A small area was hand sown due to the steep slope.
Tailings Dam 2	Woodland	319,043.07 E 6,392,347.22	2.2	<ul style="list-style-type: none"> The landform was constructed from spoil placed as an inert cap over a tailings dam. This section of the tailings dam had a layer of Redbank ash deposited on top of the tailings surface. Typical slope of the landform is 10 degrees with a primarily northerly aspect. Drainage from the slope reports to an engineered rock-lined chute. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. No topsoil was added, capping spoil has been used as the growth medium. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively. Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required The area was sown in September with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.
Woodlands RL155	Woodland	319,634.08 E 6,388,797.99 N	4.1	<ul style="list-style-type: none"> The landform was constructed from a waste emplacement. The landform has been designed using a geomorphological landform approach based on alluvial analogues. Typical slope of the landform is 6 to 14 degrees. The slope has a primarily north-easterly aspect. Drainage is via rock-lined drainage lines, directing run-off to sediment control structures to the north east. Landform surface preparation comprised bulk shaping, deep ripping, rock raking, and removal of oversize rock material. Clay loam/sandy clay loam topsoil from existing topsoil stockpiles was spread at a nominal thickness of 100mm. Soil ameliorants comprising recycled gypsum and Bettergrow Biomulch compost were applied at rates of 5t/ha and 50t/ha respectively.

Rehabilitation Site Name	Type	Coordinates (GDA94)	Area (ha)	<i>Rehabilitation Summary</i>
				<ul style="list-style-type: none"> ▪ Growth medium preparation included ameliorant incorporation, rock windrowing, rock picking, and aerating as required ▪ The area was sown in October with Diverse Native Woodland at 15.7kg/ha. Non-flowable (grass) seed was spread onto the surface using a direct drill and then the flowable components of the seed mix were spread via an air-seeder mounted on the aerator implement.

Appendix 8:

IEA Action Status Table

Audit Action Plan Status from MTW IEA 2017 (Rev C)

Reference	Non Compliance / MTW Response	Action Status Update	Target Date for Completion
SSD6464 Sch. 3, C24(a) WMP 7.4.3.1	<p>On the 6th January 2016, a sediment dam overtopped resulting in an uncontrolled discharge.</p> <p>Response/Action Description</p> <p>An internal investigation was undertaken in response to this incident. The investigation and subsequent action plan has been completed to rectify the issues at this dam and to prevent reoccurrence not only at this dam but other dams being constructed or modified. No further action is required in response to this finding.</p>	Complete.	N/A
SSD 6464 Sch.3 C.27(b)(ii) SSD 6465 Sch.3 C.25(b)(ii)	<p>The Surface Water Management Plan does not include detailed performance indicators of management objectives for Final Voids</p> <p>Response/Action Description</p> <p>MTW to update the WMP to include further detail on the performance objectives and management objectives for Final Voids, as indicated in the development consents and the EIS commitments.</p>	Complete. The MTW Mining Operations Plan includes detailed plans and rehabilitation objectives for the site, including for final voids. To address this item, a link to the Mining Operations Plan was included in an update to the Water Management Plan approved by DP&E on 20 September 2018	N/A

Reference	Non Compliance / MTW Response	Action Status Update	Target Date for Completion
MT EIS 2.4.4 (iii)	<p>No ongoing characterisation of overburden materials was conducted.</p> <p>Response/Action Description</p> <p>Extensive geochemical testing of overburden has been carried out across MTW with results showing very low risk of Acid Rock Drainage (ARD) in the overburden material being mined at MTW. The results of sampling conducted to date will be presented to DP&E to justify why ongoing characterisation of overburden materials across MTW is not required.</p>	<p>Complete.</p> <p>Presentation made to DP&E Compliance Team on 09/10/2018 to present results of overburden and interburden ARD assessments and testing conducted at MTW to illustrate why ongoing characterisation of overburden materials across MTW is not required. No further action required.</p>	N/A
AHMP 9	<p>There was no written or electronic record of which personnel had completed site specific environmental training for Cultural Heritage.</p> <p>Response/Action Description</p> <p>MTW to ensure that the AHMP and the MTW induction will cover all specific Cultural Heritage awareness requirements and that suitable training records are maintained</p>	<p>Complete.</p> <p>MTW induction has been updated and now covers all specific Cultural Heritage awareness requirements as prescribed by the AHMP. Training records are maintained by H&S Department.</p>	N/A
BMP 5.2.3	<p>On the 8-06-16 a blast was not monitored by the Bulga Village blast monitor due to a software malfunction.</p> <p>Response/Action Description</p> <p>An internal investigation identified the cause of the data loss to be isolated to a GPS fault on a single blast monitoring unit. This fault has since been corrected and no further action is required in response to this finding.</p>	Complete.	N/A

Reference	Non Compliance / MTW Response	Action Status Update	Target Date for Completion
BMP 5.2.2	<p>Blasting Controls Training was not documented</p> <p>Response/Action Description</p> <p>MTW to review process for documenting training records for training required by BMP to ensure that suitable training records are maintained.</p>	In Progress. Action item is included on MTW's action tracking system.	30/04/2020
NMP 6.2	<p>There was no substantive evidence of car-pooling encouragement programs at the time of the audit.</p> <p>Response/Action Description</p> <p>Car-pooling occurs however MTW do not run programs to specifically encourage car-pooling nor is it deemed to be necessary to do so. The Noise Management Plan will be revised to reflect this.</p>	Complete.	N/A

Reference	Non Compliance / MTW Response	Action Status Update	Target Date for Completion
20BL170012 C.9 20BL170011 C.9 20BL171930 C.8 20BL171932 C.8	<p>Water flow devices used to measure the volume of water extracted were not approved by NOW (DPI – Water). Three bore licences were found to be non-compliant with this condition; however two were decommissioned and are not in use and one related to the bore licence associated with groundwater inflow to the Warkworth Pit.</p> <p>Response/Action Description</p> <p>Following commencement of the North Coast Fractured and Porous Rock Groundwater Sources Water Sharing Plan on 1/7/2016, Licences 20BL170011 and 20BL170012 have been converted to Water Access Licences (WALs 40464 and 40465 respectively). Revised licence conditions issued by DPI Water are to be reviewed; to reflect that groundwater inflows to a pit excavation cannot be measured using a flow meter.</p> <p>Licences 20BL171930 and 20BL171932 are related to a historical methane extraction project; the bores are not in use. An investigation will be undertaken to determine if the bores should be formally abandoned and the licences relinquished, or if used for monitoring, an application sought to modify the licence purpose and conditions to reflect no water is to be abstracted.</p>	<p>Complete.</p> <p>At this point in time there are no mandatory or discretionary conditions on the works approval 20MW065009 for licenses WAL 40464 or WAL 40465 as advised by the Natural Resource Access Regulator (NRAR) during phone conversation 23/9/2018. NRAR has advised the only WAL with license conditions at this time is WAL 18233.</p>	<p>N/A</p>

Reference	Non Compliance / MTW Response	Action Status Update	Target Date for Completion
20BL170011 C.8 and C.10 20BL170012 C.8 and C.10	<p>Water flow devices used to measure the volume of water extracted were not calibrated. This related to the aforementioned bore licences that did not have flow devices attached and as such are not able to be calibrated.</p> <p>Response/Action Description</p> <p>Following commencement of the North Coast Fractured and Porous Rock Groundwater Sources Water Sharing Plan on 1/7/2016, Licences 20BL170011 and 20BL170012 have been converted to Water Access Licences (WALs 40464 and 40465 respectively). Revised licence conditions issued by DPI Water are to be reviewed; to reflect that groundwater inflows to a pit excavation cannot be measured using a flow meter.</p>	<p>Complete.</p> <p>At this point in time there are no mandatory or discretionary conditions on the works approval 20MW065009 for licenses WAL 40464 or WAL 40465 as advised by the Natural Resource Access Regulator (NRAR) during phone conversation 23/9/2018. NRAR has advised the only WAL with license conditions at this time is WAL 18233.</p>	N/A
Recommendations			
1.	<p>Complete the Salvage report for salvage work conducted in 2016.</p> <p>Response/Action Description</p> <p>A final report will be compiled to bring together the results and completed compliance actions relating to the MTW 2016 ACH salvage</p>	<p>Complete.</p> <p>2016 Compliance and Salvage Report (19 CH sites within the Stage 1 AHMP area) updated and finalised on 21/8/18.</p>	N/A

Reference	Non Compliance / MTW Response	Action Status Update	Target Date for Completion
2.	<p>MTW will determine the Wollombi Brook Probable Maximum Flood (PMF) RL at the Charlton levee and ensure there is 500mm of freeboard (from PMF to levee top RL).</p> <p>Response/Action Description</p> <p>Determine the Wollombi Brook Probable Maximum Flood (PMF) RL at the Charlton levee and ensure there is 500mm of freeboard (from PMF to levee top RL).</p>	<p>Complete.</p> <p>A review of the 2016 flood mapping by WBM BMT for Singleton Council indicates that the PMF flood level around the salt pan creek (tributary of Wollombi Brook) is approx 70.0m AHD.</p> <p>A review of MTW survey data indicates that the Charlton levee crest is maintained above RL 70.5 or higher throughout the levee length as at 17/10/2018.</p>	N/A
3.	<p>All training required by the SSD 6464 and 6465 approvals or as required by the Management Plans required by the approvals should be documented.</p> <p>Response/Action Description</p> <p>Review process for documenting training records for training required by approvals, Implement process for documenting these training records as required.</p>	In Progress. Action item is included on MTW's action tracking system.	30/04/2020