



Mount Thorley Warkworth EPL Monitoring Data

Published 19 March 2019 FOR THE MONTH ENDING 28 FEBRUARY 2019

Name of Operation	Mount Thorley Coal Loader
Environment Protection Licence	24
Licensee	Mount Thorley Coal Loading Ltd
Premises	Mount Thorley Coal Loading Ltd Mount Thorley Road, Mount Thorley Via Singleton NSW 2330
EPL Link	http://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=89660&SYSUID=1&LICID=24
Name of Operation	Mount Thorley Operations
Environment Protection Licence	1976
Licensee	Mount Thorley Operations Pty Limited
Premises	Mount Thorley Operations Mount Thorley Road Mount Thorley NSW 2330
EPL Link	https://apps.epa.nsw.gov.au/prpoeoapp/ ViewPOEOLicence.aspx?DOCID=147438&S YSUID=1&LICID=1976
Name of Operation	Warkworth Coal Mine
Environment Protection Licence	1376
Licensee	Warkworth Mining Ltd
Premises	Warkworth Coal Mine Putty Road Mount Thorley NSW 2330
EPL Link	http://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=121545&SYSUID=1&LICID=1376

1 INTRODUCTION

This report provides a summary of environmental monitoring results for Mount Thorley Warkworth (MTW) in accordance with the requirements of the following Environment Protection Licences (EPL):

- EPL24 Mount Thorley Coal Loader (MTCL);
- EPL1376 Warkworth Mining Limited (WML); and
- EPL1976 Mount Thorley Operations (MTO).

This report includes all monitoring data collected in accordance with the above licences for the period 1 to 28 February 2019.

Monitoring in this report includes:

- Air quality monitoring;
- Surface water monitoring including mine water discharge and effluent quality; and
- Blast monitoring.

Monitoring locations are shown in **Figure 1**.

2 AIR QUALITY

In accordance with the requirements of Condition M2.2 of WML EPL 1376 and MTO EPL 1976, MTW maintains a network of five PM₁₀ monitors.

Results of Particulates (PM_{10}) monitoring are shown in **Table 1**. Results reported represent the 24hr average PM_{10} , derived from 10 minute PM_{10} values for the period midnight to midnight, for each calendar date during the reporting period. The last sampling date was 28 February 2019 and the data was obtained on 1 March 2019.

YANCOAL AUSTRALIA LTD PAGE 2 OF 14

TABLE 1: PARTICULATE MATTER < 10 µM MONITORING

		Monitoring			Monitoring Point		
Date	Unit of Measure	Frequency & Capture	Warkworth North (EPA ID # 9 - WML EPL 1376)	MTO Boundary (EPA ID # 13 - MTO EPL 1976)	Dragline Crossing (EPA ID # 10 - WML EPL 1376 & MTO EPL 1976)	Heavy Vehicle Bridge (EPA ID # 11 - WML EPL 1376 & MTO EPL 1976)	MTIE (EPA ID # 12 - WML EPL 1376 & EPA ID #19 - MTO EPL 1976)
1/02/2019	μg/m³		8.6	4.0	4.5	6.2	7.6
2/02/2019	μg/m³		9.2	4.4	4.5	8.8	7.9
3/02/2019	μg/m³		13.4	6.9	9.1	14.2	10.7
4/02/2019	μg/m³		15.6	11.6	17.5	15.5	16.4
5/02/2019	μg/m³		18.2	12.1	14.1	18.3	19.4
6/02/2019	μg/m³		6.3	3.7	5.6	10.3	6.5
7/02/2019	μg/m³]	9.2	3.1	7.2	9.8	5.6
8/02/2019	μg/m³]	9.9	6.7	12.1	10.1	11.5
9/02/2019	μg/m³		5.5	5.6	12.7	8.4	10.5
10/02/2019	μg/m³]	9.3	5.8	14.3	11.8	12.4
11/02/2019	μg/m³	Continuous	9.8	6.8	#	12.5	12.4
12/02/2019	μg/m³]	13.1	5.7	31.7	18.8	19.9
13/02/2019	μg/m³]	18.9	13.8	21.3	27.2	24.5
14/02/2019	μg/m³]	9.3	5.4	8.9	15.9	10.0
15/02/2019	μg/m³	1	7.8	3.9	5.8	12.7	7.2
16/02/2019	μg/m³	1	8.4	4.7	7.6	15.5	8.1
17/02/2019	μg/m³	1	9.8	4.4	12.4	8.8	8.8
18/02/2019	μg/m³	1	#	7.8	22.6	12.3	9.9
19/02/2019	μg/m³	1	18.3	15.5	32.1	21.5	25.2
20/02/2019	μg/m³	1	12.0	6.6	7.7	10.5	12.5
21/02/2019	μg/m³	1	9.1	4.9	5.4	9.4	8.8

YANCOAL AUSTRALIA LTD

PAGE 3 OF 14

		Monitoring	Monitoring Point								
Date	Unit of Measure	Frequency & Capture	Warkworth North (EPA ID # 9 - WML EPL 1376)	MTO Boundary (EPA ID # 13 - MTO EPL 1976)	Dragline Crossing (EPA ID # 10 - WML EPL 1376 & MTO EPL 1976)	Heavy Vehicle Bridge (EPA ID # 11 - WML EPL 1376 & MTO EPL 1976)	MTIE (EPA ID # 12 - WML EPL 1376 & EPA ID #19 - MTO EPL 1976)				
22/02/2019	μg/m³		10.2	4.6	6.4	11.8	12.0				
23/02/2019	μg/m³		6.5	2.7	3.1	7.7	6.0				
24/02/2019	μg/m³		11.4	6.4	7.1	12.2	13.9				
25/02/2019	μg/m³		#	6.1	8.1	15.6	12.7				
26/02/2019	μg/m³		10.0	4.2	6.4	8.9	8.5				
27/02/2019	μg/m³		9.2	5.3	5.2	10.6	7.8				
28/02/2019	μg/m³		9.2	5.1	4.7	7.8	7.6				
	·		N	Nonthly Meaningful Data							
February	μg/m³	Minimum*	5.5	2.7	3.1	6.2	5.6				
February	μg/m³	Mean*	10.7	6.3	11.5	12.6	11.6				
February	μg/m³	Maximum*	18.9	15.5	32.1	27.2	25.2				
February	μg/m³	Median*	9.8	5.5	7.9	11.8	10.2				

^{# 24} hour data unavailable due to equipment or communications issue causing one or more missing 10 minute values

MTIE denotes Mount Thorley Industrial Estate

YANCOAL AUSTRALIA LTD PAGE 4 OF 14

^{*}Data calculated with missing 10 minute value(s) due to equipment or communication issue

3 SURFACE WATER

3.1 Mine Water Discharge Monitoring

MTW participates in the Hunter River Salinity Trading Scheme (HRSTS) and maintains two monitoring locations associated with this scheme.

MTW did not receive any discharge opportunities in the reporting period and no water was discharged as shown in **Table 2**. As such, no samples were collected during the reporting period as shown in **Table 3**.

TABLE 2: MINE WATER DISCHARGE MONITORING - VOLUME AND MASS LIMITS

Monitoring Location	Unit of measure	Volume/mass Limit	Volume/mass Discharged
Dam 9S Discharge / EPL Point 4 (MTO EPL 1976) Discharge pipe from Dam 9	Megalitres per day	100	-

TABLE 3: MINE WATER DISCHARGE MONITORING- CONCENTRATION LIMITS

Discharge Point	Date	Pollutant	Unit of measure	Licence limits	No. of samples required by licence	No. of samples you collected and analysed
Dam 1N Discharge / Point 1		Electrical Conductivity	microsiemens per centimetre	-	0	0
(WML EPL 1376)	N/A	рН	рН	6.5 - 9.0	0	0
Dam 1N Discharge Point		Total Suspended Solids	milligrams per litre	120	0	0
Dam 9S Discharge / EPL Point 4		Electrical Conductivity	microsiemens per centimetre	-	0	0
(MTO EPL 1976)	N/A	рН	рН	6.5 - 9.0	0	0
Discharge pipe from Dam 9		Total Suspended Solids	milligrams per litre	120	0	0

YANCOAL AUSTRALIA LTD

PAGE 5 OF 14

3.2 Hunter River Tributaries Monitoring

MTW undertakes monitoring in Loders Creek, in accordance with Condition M2.3 of MTO EPL 1976 as detailed in **Table 4**. Monthly sampling occurred 8 Febrary 2019 and the data was obtained 11 March 2019.

TABLE 4: HUNTER WATER TRIBUTARIES MONITORING

Monitoring Location	Pollutant	unit of measure	Monitoring frequency required by licence	No. of samples collected and analysed	Value
	Electrical Conductivity	microsiemens per centimetre	Once a month	1	1627
W5 – Loders Creek / EPL Point 3	Electrical Conductivity	microsiemens per centimetre	(min. of 4 weeks)	1	1027
(MTO EPL 1976)	рН	pH units	Once a month	1	8.0
Coal preparation plant access road bridge	μn	pri dilits	(min. of 4 weeks)	1	6.0
	Total Suspended Solids	milligrams per litre	Once a month	1	149
	Total Suspended Solids	minigrams per nice	(min. of 4 weeks)	1	149

YANCOAL AUSTRALIA LTD
PAGE 6 OF 14

3.3 Effluent Quality Monitoring

MTO undertakes monitoring in the MTO receiving lagoon (Dam 1S), in accordance with Condition M2.3 of MTO EPL 1976 as detailed in **Table 5**. Sampling is undertaken on a quarterly basis and as such no sampling was conducted in February 2019. The next sampling event will be in March 2019.

TABLE 5: EFFLUENT QUALITY MONITORING

Monitoring Location	Pollutant	unit of measure	Monitoring frequency required by licence	No. of samples collected and analysed	Value
Dam 1S / EPL Point 18	Faecal Coliforms	Colony forming units per 100 millilitres	Once a quarter	-	-
(MTO EPL 1976)	рН	pH units	Once a quarter	-	-

4 BLAST MONITORING

In accordance with the requirements of Conditions M7.1 (WML EPL 1376) and M8.1 (MTO EPL 1976), MTW maintains a network of blast monitors to measure airblast overpressure and ground vibration for all blasts carried out at MTW.

During the reporting period one blast exceeded the 115dB(L) threshold for airblast overpressure at the MTIE blast monitor on 6 February 2019 and no blasts exceeded the 5mm/s threshold for ground vibration.

Blast monitoring results are detailed in **Table 6** (Airblast Overpressure) and **Table 7** (Ground Vibration). The last date sampled was on 28 February 2019. The data was obtained on 1 March 2019.

YANCOAL AUSTRALIA LTD
PAGE 7 OF 14

TABLE 6: BLAST MONITORING (AIRBLAST OVERPRESSURE)

				EPL L	imits			Monitoring Poin	t	
Biast ID	Date and Time	Unit of Measure	Monitoring Frequency & Capture	95% of Blasts	100% of Blasts	Bulga Village EPA ID # 6 (EPL 1376) & EPA ID # 7 (EPL 1976)	Wambo Road EPA ID # 5 (EPL 1376) & EPA ID # 6 (EPL 1976)	Putty Rd MTIE EPA ID # 8 (EPL 1376) & EPA ID # 9 (EPL 1976)	Warkworth EPA ID # 4 (EPL 1376) & EPA ID # 5 (EPL 1976)	Wollemi Peak Road EPA ID # 7 (EPL 1376) & EPA ID # 8 (EPL 1976)
w30-gmd-ptg3	1/02/2019 12:16	dB(L)		115	120	96.5	99.9	107.9	102.4	91.9
w33-wnb-ps2	4/02/2019 13:51	dB(L)		115	120	93.0	107.0	99.3	102.7	91.9
n37-whf-pr2	5/02/2019 12:19	dB(L)		115	120	99.0	106.6	97.1	95.6	97.9
w30-gmb-whc-co2 & w30-gmd-ptg4	6/02/2019 14:16	dB(L)		115	120	100.9	99.9	116.9	101.1	99.4
n37-gmc-ps1	7/02/2019 16:23	dB(L)		115	120	94.5	94.6	101.5	92.0	103.5
w36-rcd-pr6	8/02/2019 9:36	dB(L)	All Blasts 100%	115	120	102.0	99.6	95.5	88.4	101.2
n37-whf-pr3	8/02/2019 12:23	dB(L)		115	120	98.8	106.2	102.1	102.5	90.8
w36-rcd-pr7	13/02/2019 12:39	dB(L)		115	120	103.2	103.9	94.8	97.1	103.0
n41-bla-ptg15	13/02/2019 13:37	dB(L)		115	120	97.2	98.4	98.4	96.8	87.1
n41-ble-pr3	14/02/2019 12:59	dB(L)		115	120	106.0	99.0	104.3	100.4	101.0
n32-wwa-ptg5	15/02/2019 12:15	dB(L)		115	120	110.5	94.5	106.6	100.8	103.7

YANCOAL AUSTRALIA LTD

PAGE 8 OF 14

				EPL L	imits			Monitoring Poin	t	
Blast ID Da	Date and Time	Unit of Measure	Monitoring Frequency & Capture	95% of Blasts	100% of Blasts	Bulga Village EPA ID # 6 (EPL 1376) & EPA ID # 7 (EPL 1976)	Wambo Road EPA ID # 5 (EPL 1376) & EPA ID # 6 (EPL 1976)	Putty Rd MTIE EPA ID # 8 (EPL 1376) & EPA ID # 9 (EPL 1976)	Warkworth EPA ID # 4 (EPL 1376) & EPA ID # 5 (EPL 1976)	Wollemi Peak Road EPA ID # 7 (EPL 1376) & EPA ID # 8 (EPL 1976)
l54-wba-md1 & l54- wba-ps1	19/02/2019 13:15	dB(L)		115	120	100.5	104.0	107.9	92.4	109.7
I54-rcd-ptg1 & I54-wba- ps1	19/02/2019 13:19	dB(L)		115	120	108.3	106.4	113.0	96.1	97.5
w36-rcd-pr8	20/02/2019 13:13	dB(L)		115	120	100.1	102.4	105.0	103.0	100.0
n37-gmc-ps2 & n34- bfa-ps3	20/02/2019 14:17	dB(L)		115	120	87.9	107.6	102.7	95.9	108.7
w30-gmd-whc-co1 & w30-gmd-ptg5	21/02/2019 12:42	dB(L)		115	120	105.0	103.7	110.2	99.2	102.1
n37-gmc-pr1	22/02/2019 12:26	dB(L)		115	120	104.6	108.9	114.0	110.0	101.9
n37-whf-pr4	23/02/2019 10:59	dB(L)		115	120	99.7	99.2	97.1	104.0	106.2
w27-wwe-k-co5 & w34- wba-ptg2	26/02/2019 12:21	dB(L)		115	120	94.4	90.9	92.0	91.9	95.7
n43-wba-ps8	26/02/2019 13:11	dB(L)		115	120	102.2	99.9	98.5	90.7	93.3
n37-gmc-pr2	27/02/2019 13:17	dB(L)		115	120	109.6	109.6	108.1	104.6	113.4
w30-wha-c-co1 & w30- gmd-whc-co2	28/02/2019 12:17	dB(L)		115	120	98.0	95.2	103.6	100.5	96.3
n43-rcf-pr1	28/02/2019 14:31	dB(L)		115	120	99.1	106.9	104.0	106.0	103.3

YANCOAL AUSTRALIA LTD
PAGE 9 OF 14

			Monitoring Frequency & Capture	EPL L	imits	Monitoring Point					
Blast ID	Blast ID Date and Time	Unit of Measure		95% of Blasts	100% of Blasts	Bulga Village EPA ID # 6 (EPL 1376) & EPA ID # 7 (EPL 1976)	Wambo Road EPA ID # 5 (EPL 1376) & EPA ID # 6 (EPL 1976)	Putty Rd MTIE EPA ID # 8 (EPL 1376) & EPA ID # 9 (EPL 1976)	Warkworth EPA ID # 4 (EPL 1376) & EPA ID # 5 (EPL 1976)	Wollemi Peak Road EPA ID # 7 (EPL 1376) & EPA ID # 8 (EPL 1976)	
				Monthly	/ Meaningful	Data					
Minimum	February	dB(L)		115	120	87.9	90.9	92.0	88.4	87.1	
Mean	February	dB(L)		115	120	100.5	101.9	103.5	98.9	100.0	
Maximum	February	dB(L)		115	120	110.5	109.6	116.9	110.0	113.4	
Median	February	dB(L)		115	120	100.1	102.4	103.6	100.4	101.0	

YANCOAL AUSTRALIA LTD
PAGE 10 OF 14

TABLE 7: BLAST MONITORING (GROUND VIBRATION)

				EPL L	imits			Monitoring Poin	it	
Biast ID	Date and Time	Unit of Measure	Monitoring Frequency & Capture	95% of Blasts	100% of Blasts	Bulga Village EPA ID # 6 (EPL 1376) & EPA ID # 7 (EPL 1976)	Wambo Road EPA ID # 5 (EPL 1376) & EPA ID # 6 (EPL 1976)	Putty Rd MTIE EPA ID # 8 (EPL 1376) & EPA ID # 9 (EPL 1976)	Warkworth EPA ID # 4 (EPL 1376) & EPA ID # 5 (EPL 1976)	Wollemi Peak Road EPA ID # 7 (EPL 1376) & EPA ID # 8 (EPL 1976)
w30-gmd-ptg3	1/02/2019 12:16	mm/s		5	10	0.2	0.1	0.1	0.1	0.1
w33-wnb-ps2	4/02/2019 13:51	mm/s		5	10	0.9	3.3	0.3	2.1	0.8
n37-whf-pr2	5/02/2019 12:19	mm/s		5	10	0.1	0.1	0.1	0.2	0.1
w30-gmb-whc-co2 & w30-gmd-ptg4	6/02/2019 14:16	mm/s		5	10	0.2	0.1	0.1	0.1	0.1
n37-gmc-ps1	7/02/2019 16:23	mm/s		5	10	0.3	0.3	0.1	0.5	0.2
w36-rcd-pr6	8/02/2019 9:36	mm/s	All Blasts 100%	5	10	2.0	1.1	0.2	0.5	1.4
n37-whf-pr3	8/02/2019 12:23	mm/s		5	10	0.4	0.3	0.1	0.3	0.2
w36-rcd-pr7	13/02/2019 12:39	mm/s		5	10	1.7	1.3	0.2	0.5	1.7
n41-bla-ptg15	13/02/2019 13:37	mm/s		5	10	0.1	0.1	0.1	0.2	0.1
n41-ble-pr3	14/02/2019 12:59	mm/s		5	10	0.1	0.3	0.1	0.3	0.1
n32-wwa-ptg5	15/02/2019 12:15	mm/s		5	10	0.1	0.2	0.1	0.2	0.1

YANCOAL AUSTRALIA LTD
PAGE 11 OF 14

				EPL L	imits			Monitoring Poin	t	
Blast ID Date	Date and Time	Unit of Measure	Monitoring Frequency & Capture	95% of Blasts	100% of Blasts	Bulga Village EPA ID # 6 (EPL 1376) & EPA ID # 7 (EPL 1976)	Wambo Road EPA ID # 5 (EPL 1376) & EPA ID # 6 (EPL 1976)	Putty Rd MTIE EPA ID # 8 (EPL 1376) & EPA ID # 9 (EPL 1976)	Warkworth EPA ID # 4 (EPL 1376) & EPA ID # 5 (EPL 1976)	Wollemi Peak Road EPA ID # 7 (EPL 1376) & EPA ID # 8 (EPL 1976)
l54-wba-md1 & l54- wba-ps1	19/02/2019 13:15	mm/s		5	10	0.8	0.5	0.2	0.2	1.0
l54-rcd-ptg1 & l54-wba- ps1	19/02/2019 13:19	mm/s		5	10	0.6	0.5	0.1	0.4	1.0
w36-rcd-pr8	20/02/2019 13:13	mm/s		5	10	2.1	1.6	0.2	0.6	1.2
n37-gmc-ps2 & n34- bfa-ps3	20/02/2019 14:17	mm/s		5	10	0.5	0.6	0.3	0.6	0.4
w30-gmd-whc-co1 & w30-gmd-ptg5	21/02/2019 12:42	mm/s		5	10	0.1	0.1	0.1	0.1	0.1
n37-gmc-pr1	22/02/2019 12:26	mm/s		5	10	0.3	0.3	0.1	0.5	0.2
n37-whf-pr4	23/02/2019 10:59	mm/s		5	10	0.2	0.2	0.1	0.2	0.1
w27-wwe-k-co5 & w34- wba-ptg2	26/02/2019 12:21	mm/s		5	10	0.1	0.1	0.1	0.3	0.1
n43-wba-ps8	26/02/2019 13:11	mm/s		5	10	0.2	0.3	0.1	0.2	0.1
n37-gmc-pr2	27/02/2019 13:17	mm/s		5	10	0.3	0.3	0.2	0.5	0.3
w30-wha-c-co1 & w30- gmd-whc-co2	28/02/2019 12:17	mm/s		5	10	0.1	0.1	0.1	0.3	0.1
n43-rcf-pr1	28/02/2019 14:31	mm/s		5	10	0.6	0.6	0.2	1.2	0.4

YANCOAL AUSTRALIA LTD
PAGE 12 OF 14

Blast ID	Date and Time	Unit of Measure	Monitoring Frequency & Capture	EPL Limits		Monitoring Point				
				95% of Blasts	100% of Blasts	Bulga Village EPA ID # 6 (EPL 1376) & EPA ID # 7 (EPL 1976)	Wambo Road EPA ID # 5 (EPL 1376) & EPA ID # 6 (EPL 1976)	Putty Rd MTIE EPA ID # 8 (EPL 1376) & EPA ID # 9 (EPL 1976)	Warkworth EPA ID # 4 (EPL 1376) & EPA ID # 5 (EPL 1976)	Wollemi Peak Road EPA ID # 7 (EPL 1376) & EPA ID # 8 (EPL 1976)
Monthly Meaningful Data										
Minimum	February	mm/s		5	10	0.08	0.06	0.08	0.10	0.05
Mean	February	mm/s		5	10	0.51	0.53	0.14	0.44	0.42
Maximum	February	mm/s		5	10	2.11	3.28	0.29	2.06	1.69
Median	February	mm/s		5	10	0.25	0.29	0.11	0.32	0.18

YANCOAL AUSTRALIA LTD
PAGE 13 OF 14




Figure 1: Mount Thorley Warkworth Environmental Monitoring Locations

YANCOAL AUSTRALIA LTD PAGE 14 OF 14